

TMS320LF2401A, TMS320LC2401A

DSP Controller

Silicon Errata

SPRZ013G
December 2001
Revised June 2005



Copyright © 2005, Texas Instruments Incorporated

Contents

1	Introduction	3
1.1	Quality and Reliability Conditions	3
	TMX Definition	3
	TMP Definition	3
	TMS Definition	3
1.2	Revision Identification	4
2	Known Design Marginality/Exceptions to Functional Specifications	5
	Maximum CLKIN frequency while using boot-ROM SCI loader	5
	Internal Oscillator	5
	ADC Sequencer Operation	5
	XF/TMS Pin Function	6
3	Documentation Support	7

1 Introduction

This document describes the silicon updates to the functional specifications for the TMS320LF2401A DSP Controller (silicon revisions 0, A, B, and C) and TMS320LC2401A DSP Controller. The updates are applicable to one or both of the following:

- TMS320LF2401A (32-pin LQFP, VF suffix)
- TMS320LC2401A (32-pin LQFP, VF suffix)

1.1 Quality and Reliability Conditions

TMX Definition

Texas Instruments (TI) does not warranty either (1) electrical performance to specification, or (2) product reliability for products classified as “TMX.” By definition, the product has not completed data sheet verification or reliability performance qualification according to TI Quality Systems Specifications.

The mere fact that a “TMX” device was tested over a particular temperature range and voltage range should not, in any way, be construed as a warranty of performance.

TMP Definition

TI does not warranty product reliability for products classified as “TMP.” By definition, the product has not completed reliability performance qualification according to TI Quality Systems Specifications; however, products are tested to a published electrical and mechanical specification.

TMS Definition


Fully-qualified production device.

All trademarks are the property of their respective owners.

1.2 Revision Identification for TMS320LF2401A

The silicon revision can be determined by the second letter to the right of the TI EIA (Electronics Industries Association) code (980) as shown on the top of the package in Figure 1.

Figure 1. Example, Silicon Revision Code for TMS320LF2401A (VF)



Second Letter After TI EIA Code	Silicon Revision	Comments
Blank (no second letter)	Indicates Revision 0	This silicon revision is available as TMX only.
A	Indicates Revision A	This silicon revision is available as TMX only.
B	Indicates Revision B	This silicon revision is available as TMX only.
C	Indicates Revision C	This silicon revision is available as TMS.

2 Known Design Marginality/Exceptions to Functional Specifications

Advisory

Maximum CLKIN frequency while using boot-ROM SCI loader

Revision(s) Affected: TMS320LF2401A – Revisions 0, A, B, and C
TMS320LC2401A

Details: The SCI boot loader briefly sets the PLL to x4 prior to checking whether the PLL must be set to x2. If a CLKIN frequency greater than 10 MHz is used, this could result in operating the device at frequencies greater than 40 MHz.

Workaround: CLKIN frequency should not exceed 10 MHz if the boot-ROM SCI loader is used.

Advisory

Internal Oscillator

Revision(s) Affected: TMS320LF2401A – Revisions 0, A, B, and C

Details: The internal oscillator of the 2401A device has a design marginality that may prevent the internal oscillator from starting upon power-up under certain conditions pertaining to board layout, ground bounce, and power-supply ramp rate. This is a concern only when the internal oscillator is used in conjunction with an external quartz crystal/ceramic resonator and not with an external oscillator.

Workaround: Use of a 1M- Ω resistor in parallel with the crystal across the XTAL1 and XTAL2 pins removes this condition.

Advisory

ADC Sequencer Operation

Revision(s) Affected: TMS320LF2401A – Revisions 0, A, B, and C
TMS320LC2401A

Details: The ADC sequencer operation has an issue when $CPS = 1$ and $ACQ_Prescaler = 0$. When an ADC sequence is started, the sequence stops after performing the first conversion. For example, if there are five conversions programmed for a sequence, the sequencer may stop after performing the first conversion. When $CPS = 0$, all the conversions are performed. The issue surfaces only when $CPS = 1$ and $ACQ_Prescaler = 0$. CPS can be 1 for any other $ACQ_Prescaler$ value.

Workaround: $ACQ_Prescaler = 0$ should not be used in conjunction with $CPS = 1$.

Advisory*XF/TMS Pin Function*

Revision(s) Affected: TMS320LF2401A – Revisions 0, A, B, and C

Details: The XF output function is multiplexed with the JTAG TMS input function onto the same pin. When the $\overline{\text{TRST}}$ pin is high, the XF/TMS pin is configured as a TMS input and when the $\overline{\text{TRST}}$ pin is low, it is configured as an XF output pin. The problem arises in that at certain times, it is legal for a scan controller to drive the TMS pin while pulling $\overline{\text{TRST}}$ low to reset the JTAG logic. If the state of the XF output function is opposite the state that the scan controller drives onto TMS, a drive conflict will arise between the device and the scan controller. Over time, this can potentially degrade the reliability of the output buffer on the XF/TMS pin, as well as potentially damaging the scan controller.

Workaround: This has been fixed in the C revision of the silicon. An XF-enable bit was added to the design as bit 0 of address 0x701B. This register is labeled SCSR4. The bit will come up out of reset as a zero, with XF output disabled. If you write a one to this bit, the XF output will be enabled (assuming $\overline{\text{TRST}}$ is low). This bit is not readable.

3 Documentation Support

For device-specific data sheets and related documentation, visit the TI web site at: <http://www.ti.com>

To access documentation on the web site:

1. Go to <http://www.ti.com>
2. Click on **DSP Product Tree**
3. Click on the **C2000** tab
4. Click on **TMS320C24x DSP Generation**
5. Click on a device name and then click on the documentation type you prefer.

For further information regarding the TMS320LF2401A, please refer to the following publications:

- *TMS320LF/LC240xA DSP Controllers Reference Guide: System and Peripherals* (literature number SPRU357)
- Manual Update Sheet for *TMS320LF/LC240xA DSP Controllers Reference Guide: System and Peripherals* (SPRU357B) [literature number SPRZ015]
- *TMS320F/C24x DSP Controllers Reference Guide: CPU and Instruction Set* (literature number SPRU160)
- *3.3V DSP for Digital Motor Control* application report (literature number SPRA550)
- *TMS320LF2401A, TMS320LC2401A DSP Controllers* data sheet (literature number SPRS161)

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products		Applications	
Amplifiers	amplifier.ti.com	Audio	www.ti.com/audio
Data Converters	dataconverter.ti.com	Automotive	www.ti.com/automotive
DSP	dsp.ti.com	Broadband	www.ti.com/broadband
Interface	interface.ti.com	Digital Control	www.ti.com/digitalcontrol
Logic	logic.ti.com	Military	www.ti.com/military
Power Mgmt	power.ti.com	Optical Networking	www.ti.com/opticalnetwork
Microcontrollers	microcontroller.ti.com	Security	www.ti.com/security
		Telephony	www.ti.com/telephony
		Video & Imaging	www.ti.com/video
		Wireless	www.ti.com/wireless

Mailing Address: Texas Instruments
Post Office Box 655303 Dallas, Texas 75265