ZZ4 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.

ZZ3 ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.

ZZ2 ■ These assemblies are ESD sensitive, ESD precautions shall be observed.

ZZ1 ■ Install label in silkscreened box after final wash. Text shall be 8 pt font. Text shall be per the Label Table in the PDF schematic.

J1

J2

U5

C26

R39

U26A

U26B

C49

C37

J5

R53

R54

L2

C55

R41

R29

C4

C13

C15

R32

U9

U19

L3

C52

C56

U20

C53

C50

C51

R36

S1

J3

C48

R52

C58

U4

U21

R27

U12

S2

C17

C18

J6

R10

R8

R9

R7

U4