ZZ3 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.

ZZ2 ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.

ZZ1 ■ These assemblies are ESD sensitive, ESD precautions shall be observed.




COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.
ASSEMBLY VARIANT: 001

| | | | |
|---|---|---|---|
| PCB VIEWED FROM TOP SIDE | BOARD #: MCU133 | REV: A | SVN REV: Unknown revision |
| M5 Assembly Top | TID #: N/A | | |
| PLOT NAME = Top Assembly Drawing | GENERATED : 4/5/2024 7:10:52 PM | | TEXAS INSTRUMENTS |




COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.
ASSEMBLY VARIANT: 001

| | | | |
|---|---|---|---|
| PCB VIEWED FROM BOTTOM SIDE | BOARD #: MCU133 | REV: A | SVN REV: Unknown revision |
| | TID #: N/A | | |
| PLOT NAME = Bottom Assembly Drawing | GENERATED : 4/5/2024 7:10:52 PM | | TEXAS INSTRUMENTS |