

FIX Feb 5 -- Low leak, 2 x 100
FIX Feb 5 -- Low leak, 2 x 100
FIX MAR 25
add wire to ONE4 (was floating)
change 5V to +5V to connect to proper net.
T_STRIP3
U905 ADG1408
U920 ADG467BRZ
U903 MAX354CWE
U904 MAX354CWE
U901 ADG1408
U909 ADG467BRZ
U902 ADG1408
U919 ADG467BRZ
U921 CD74HC138PWR
U963 BAT754S.215
U964 BAT754S.215
U965 SDM40E20LS
RN902 100k Network
Vout TP_8PIN
CH_READ TP_8PIN
GND_SEN TP_8PIN
ONE_W TP_8PIN
J0 DB37M_W_SHLD
J1 DB37M_W_SHLD
Title
Size C
Number
Revision
Date: 8/25/2015
Sheet of
File: G:\EVM Release and General Info\...\proj_14.SchDoc