



ZZ2 ■ These assemblies are ESD sensitive, ESD precautions shall be observed.  
ZZ3 ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.  
ZZ4 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.  
ASSEMBLY VARIANT: 001

PCB VIEWED FROM TOP SIDE	BOARD #: MSA005	REV: A	SVN REV: Not In VersionControl
	TID #:		
PLOT NAME = Top Assembly Drawing	GENERATED : 12/18/2015 9:55:43 AM	TEXAS INSTRUMENTS	



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.  
ASSEMBLY VARIANT: 001

PCB VIEWED FROM BOTTOM SIDE	BOARD #: MSA005	REV: A	SVN REV: Not In VersionControl
	TID #:		
PLOT NAME = Bottom Assembly Drawing	GENERATED : 12/18/2015 9:55:43 AM		TEXAS INSTRUMENTS