



THIS DRAWING IS INTENDED TO HELP IN THE ASSEMBLY OF THE DESIGN.

1. REFER TO ODB++ FILE FOR SPECIFIC COMPONENT LOCATION INFORMATION.
2. FINISHED BOARD SHALL BE RoHS COMPLIANT AND LEAD FREE ASSEMBLY.
3. REMOVE THE METAL TAB ON ALL OF THE BANANA JACKS BEFORE MOUNTING ON THE BOARD. USE LOCTITE THREADLOCKER BLUE 242 (OR EQUIVALENT) WHEN INSTALLING THE BANANA JACKS.

| REVISIONS | | | | |
|-----------|-----|-------------|--|------|
| ZONE | LTR | DESCRIPTION | | DATE |
| | | | | |

| | | | | | | | | |
|---|-----------------------|--|------------------------|----------------|---------------------------------|--|--------------|--|
| UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES ARE: FRACTIONS DECIMALS ANGLES +/- .XX +/- .01 +/- .XXX +/- .005 +/- | CONTRACT NO. | | TEXAS INSTRUMENTS INC. | | | | | |
| | APPROVALS | | DATE | | ASSEMBLY DRAWING ADS5402 EVM | | | |
| | DRAWN JV SMITH | | 01-27-12 | | | | | |
| | ENGR R. PRENTICE | | 01-27-12 | | | | | |
| MATERIAL | | | | | | | | |
| SEE NOTE 5 | | | | | | | | |
| | | | | | | | | |
| FINISH | | | SIZE | CODE IDENT NO. | DRAWING NO. | | REV. | |
| SEE NOTES 7, 8, 9 | | | B | | | | A | |
| DO NOT SCALE DRAWING | | | SCALE | NONE | | | SHEET 1 OF 1 | |